Update firmware 3.3.1

- Bug fixes
  - When a user patch was deleted, the old name and category were not deleted.
  - Poly-Aftertouch improvement.
  - In Split and Layer modes, the patch selector is now set to Patch B by default.

- New menu Settings

 Saved in the patch.

  Global Patch : :

  - **Detune VCO2 max**: detune VCO2 from 1 to 12 semitones, default is 7.
  - **Detune VCO2 quantized**: On/Off, default is Off.
  - **Detune Voices semitone**: default is 1.
  - **Round Robin**: On, channels are selected based on their occupancy. Off, channels are chosen sequentially from 1 to 10.

- Modification of the Global Parameters menu: as a result:
  - **Range Pitch bend**: 2
  - **Range Amount glide**: 4
  - **Max Time Glide / Portamento**: 1, 3, 10, 30.
  - **Load FX with Patch**: On/Off

- Added an **offse**t to Velocity Assign identical to Assign Expression Pedal.

- New screen when adjusting **VCO2 Detune**. Coarse with the potentiometer and fine with the "Value" encoder.

- New modulations:
    Now you can create an assignment with the "Assign" buttons for the envelope, velocity, mod wheel, Aftertouch and LFO1, LFO2, on the VCO frequency by pressing **Assign and Octave + or -.** This is equivalent to adding positive or negative modulations to FM1 and/or FM2 in addition to the pre-assignments.

- Removal of the Poly-aftertouch Yes/No line from the Keyboard utilities menu. Detection is now automatic.